FIG. 1





FIG. 2



3/25

FIG. 3




FIG. 4





FIG. 5



5/25

FIG. 6




FIG. 7






FIG. 8



:

FIG. 9



7/25

FIG. 10A








FIG. 10B






8/25








10/25

FIG. 14



A

FIG. 15




FIG. 16A





FIG. 16B



13/25

FIG. 17





FIG. 18



15/25

FIG. 19






FIG. 20



á

FIG. 21



17/25




FIG. 23




FIG. 24




FIG. 25







FIG. 26







Kazumasa KOKURA, et al.
CARGO HANDLING VEHICLE

21/25

FIG. 28




FIG. 29A






FIG. 29B



23/25



24/25




FIG. 31B

2b

41

41

40a

40b

-2a

100

FIG. 32

